

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H1592		Bullnose Rail Filler	PL	F	-	F
			1	B	-	F
			2	A	A1	F
			3	A	A1	F
			4	B	-	F
			5	A	-	F
			6	A	A1	F
			7	A	A1	F
			8	A	-	F
			9	A	-	F
			10	B	-	F
			11	A	-	F
			12	D	-	F
			13	A	-	F
			14	B	-	F
			15	A	A1	F
			16	A	-	F
			17	B	-	F
			18	New	-	F
			19	New	-1	F
			20	New	-	F
			21	New	-	F
			22	New	-	F
			23	New	-	F
			24	New	-1,-2	F
			25	New	-	F
			26	New	-	F
			27	New	-	F
			28	New	-	F
			29	New	-	F
			30	New	-	F
			31	New	-1	F
			32	New	-	F
			33	New	-1	F
			34	New	-	F
			35	New	-	F
			36	New	-	F
			37	New	-	F
			38	New	-	F
			39	New	-	F
			40	New	-	F
			41	New	-	F
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	HEATHTECNA <div> Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226 </div>			Model No 737	
J. Dodd	Feb. 9, 2004				Page 7.7 REV H	


**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H1592, cont.			42	New	-	F
			43	New	-	F
			44	New	-	F
			45	New	-	F
			46	New	-	F
			47	New	-	F
			48	New	-	F
			49	New	-	F
			50	New	-	F
			51	New	-	F
			52	New	-	F
			53	New	-	F
			54	A	-	F
			55	New	-1	F
			56	New	-	F
			57	A	-	F
			58	B	-	F
			59	New	-	F
			60	New	-1	F
			Prepared by	Date	Title	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	<div>Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226</div> <div>HEATHTECNA</div>			Model No	
J. Dodd	Feb. 9, 2004				737	
Page 7.8 REV H						

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H1596		Intercostal Assembly - Forward Bin Modification (737-300)	PL	New	-1,-2	E
			1	New	-1	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
H1597		Support Details - Forward Bin Modification (737-300)	PL	New	-1	E
			1	New	-1	E
			2	New	-1	E
			3	New	-	E
			4	New	-1	E
H1796		Placard – One Line	BK	A	-	E
H1881 (23-30-17)		Wiring Diagram - Video Monitor System - Australia	1	A	-	G
			2	A	-	G
			3	A	-	G
			4	A	-	G
			5	A	-	G
			6	A	-	G
H1906 (23-31-01)		Wiring Diagram - Passenger Address - Attendants Panel	1	New	-	F
			2	New	-	F
H1914 (23-34-02)		Wiring Diagram - Audio Entertainment Distribution	1	A	-	G
			2	New	-	G
			3	New	-	G
H1936 (23-32-02)		Wiring Diagram - Video System	1	New	-	F
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	<div>Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226</div> <div>HEATHTECNA</div>			Model No	
J. Dodd	Feb. 9, 2004				737	
Page 7.9 REV H						


**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H1939 (31-31-03)		Wiring Diagram - DFDRS Interconnect - Group 3	1 2 3	New New New	- - -	F F F
H1948 (35-21-31)		Wiring Diagram - Passenger Oxygen System - Left Side	1	New	-	F
H1956 (33-22-31)		Wiring Diagram - Fluorescent Lighting Ceiling – Right	1 2	New New	- -	F F
H1967 (33-25-21)		Wiring Diagram - Passenger Signs – Left Side - Forward	1 2	New New	- -	F F
H1981 (33-26-11)		Wiring Diagram - Attendants Work Lights	1	New	-	F
H1997 (33-26-31)		Wiring Diagram - Lavatory Lights and Signs	1 2 3	New New New	- - -	F F F
Prepared by C. Zilinek	Date Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			Report No. HPD-DL-68	
Checked by J. Dodd	Date Feb. 9, 2004	 Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No 737	Page 7.10 REV H


**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2014	-1 [125,135, 137,143] -3 [131]	Structures Rework - Bin Support, Forward 737-400	PL	C	-	H
			1	New	-	E
			2	A	-	H
			3	New	-	E
			4	New	-	E
			5	A	-	H
			6	New	-	E
			7	A	-	F
			8	A	-	F
			9	New	-	E
			10	A	-	H
			11	B	-	H
H2015		Structure Details / Assy - Bin Support, Forward, 737-400	PL	A	-	E
			1	New	-1	E
			2	A	-	E
			3	New	-	E
			4	New	-	E
H2016		Intercostal Assembly - Bin Support, Forward, 737-400	PL	A	A1	F
			1	A	-	E
			2	B	-	F
H2017	-1 [125,135, 143] -3 [131]	Bin Installation – Rework	PL	A	A1,A2	F
			1	New	-	E
			2	A	-	F
			3	A	-	F

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2018		Bin Assembly – Reduced/ Reduced	PL	A	-	F
			1	New	-1	F
			2	New	-	E
			3	A	-	F
H2019		Panel Assembly – 737, Overhead Stowage	PL	A	-	E
			1	New	-	E
			2	New	-	E
			3	A	-	E
H2020	-1 [135, 143] -3 [137] -5 [125]	Sidewall Installation - Rework	PL	A	-	F
			1	A	-	F
			2	A	-	F
			3	New	-	E
			4	New	-	E
			5	New	-	F
			6	New	-	F
H2021	-1 [135,137, -143] -3 [125]	Window Installation - Rework	PL	D	-	H
			1	New	-	E
			2	A	-	F
H2022	-1 [125,135, 137,143] -3 [137]	Lowered Ceiling Installation – Rework	PL	D	-	H
			1	New	-	E
			2	New	-	E
			3	B	-	G
			4	New	-	E
			5	A	-	H
			6	A	-	H
			7	B	-	G
			8	New	-	E
			9	New	-	E
			10	New	-	E
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date				Model No	
J. Dodd	Feb. 9, 2004	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			737 Page 7.12 REV H	

Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for Model 737-400 Series Airplanes

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2023	-1 [125,135,143] -3 [137]	PSU Installation – 737-400	PL	New	-1	H
			1	New	-1	H
			2	New	-	E
			3	New	-	E
H2024	-1 [125,135,137,143]	Passenger Seat Installation (737-400)	PL	B	B1,B2	H
			1	C	C1	H
H2025	-1 [125,135,143] -3 [137]	Rework Installation - Systems, Forward, 737-400	PL	New	-1,-2,-3	F
			1	New	-	E
			2	New	-1	F
			3	New	-	E
			4	A	-	F
			5	B	-	F
			6	New	-1	E
			7	New	-1	F
H2026	-1,-3 [125,135,137,143]	Rework – Floor Structure	PL	G	-	H
			1	C	-	H
			2	D	-	H
			3	B	-	H
			4	C	-	H
			5	B	-	H
			6	ZZ	-	F
			7	ZZ	-	F
			8	C	-	H
			9	D	-	G
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	 Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No	737
J. Dodd	Feb. 9, 2004				Page	7.13 REV H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2027		Assembly – Ceiling Light	PL	New	-1,-2,-3,-4	F
			1	A	A1	F
			2	New	-	E
			3	New	-	E
H2028		Detail – Ceiling Light	PL	New	-	F
			1	New	-	F
			2	A	-	F
			3	New	-	F
			4	A	-	F
			5	New	-	F
H2029		Bin Details – Metallic	PL	B	-	F
			1	New	-	E
			2	A	-	E
			3	New	-	F
H2030		Lowered Ceiling Assembly – Header	PL	A	-	F
			1	A	-	F
			2	New	-	E
			3	New	-1	F
H2031		Lowered Ceiling Details - Metal	PL	New	-	E
			1	New	-	E

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2032		Panel Assembly - Lowered Ceiling	PL	E	E1	H
			1	New	-	G
			2	B	-	G
			3	New	-	E
			4	A	-	H
			5	A	-	F
			6	New	-	E
			7	New	-	E
			8	New	-	E
			9	A	A1	H
			10	New	-	F
			11	New	-	F
			12	New	-1	G
H2033	-1 [125,135, 137,143]	Installation – Raceway IFE/Power	PL	A	-	F
			1	New	-	E
			2	A	-	F
H2034		Sidewall Duct Assembly, Light Provision, Forward, 737-400	PL	A	A1,A2	H
			1	A	A1	H
			2	New	-	E
			3	New	-	E
			4	New	-	E
H2035		Extrusion Details - Sidewall Duct, Fwd. 737-400	PL	New	-1,-2	H
			1	C	-	H
			2	A	-	F
			3	A	-	F
			4	New	-	F
H2036	-3 [125,137, 143]	QAR Relocation – 737-400	PL	B	-	F
			1	A	-	E
			2	B	-	F
			3	New		F
Prepared by		Date	Title			Report No.
C. Zilinek		Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68
Checked by.		Date	<div>Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226</div> <div>HEATHTECNA</div>			Model No
J. Dodd		Feb. 9, 2004				737
						Page 7.15 REV H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2038		Carpet Riser – Rework	PL	C	-	F
			1	C	-	F
			2	C	-	F
			3	C	-	F
			4	New	-	F
			5	New	-	F
H2039	-1 [125,135, 137,143]	Gaspar Air (PSU) – Rework	PL	New	-1	F
			1	A	-	F
H2040		Details – Sheet Metal, Sidewall Duct, 737-400	PL	New	-	F
			1	New	-	F
H2041	-1 [125,135, 137,143]	Emergency Equipment Relocation – 737	PL	A	A1	E
			1	B	-	E
			2	B	-	E
H2042		Details – Machined, Sidewall Duct, 737-400	PL	New	-1	F
			1	New	-	E
			2	A	-	F
H2043		Diffuser Assembly - Forward, 737-400	PL	New	-1,-2,-3	H
			1	New	-	E

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2045		Details – Floor Structure	PL	B	-	H
			1	New	-	F
			2	A	-	F
			3	A	-	F
			4	New	-	F
			5	New	-	F
			6	A	-	F
			7	A	-	F
			8	A	-	F
			9	New	-	F
			10	New	-	F
			11	A	-	G
			12	New	-	F
			13	New	-	G
			14	New	-	H
			15	New	-	H
			16	New	-	H
H2046		Tray Assembly – Modified, QAR	PL	New	-	F
			1	New	-	F
H2047		Bracket Detail – Disconnect	PL	New	-	F
			1	New	-	F

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2632		Details – SuperBin III	PL	L	L1,L2,L3	E
			1	A	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
			5	New	-	E
			6	New	-	E
			7	A	-	E
			8	A	-	E
			9	A	-	E
			10	New	-	E
			11	New	-	E
			12	A	-	E
			13	New	-1	E
			14	New	-	E
			15	A	-	E
			16	A	-	E
			17	A	-	E
			18	New	-	E
			19	New	-	E
			20	New	-	E
			21	A	-	E
			22	New	-	E
			23	New	-	E
			24	New	-	E
			25	New	-	E
			26	A	-	E
			27	New	-	E
			28	New	-	E
			29	B	-	E
			30	B	-	E
			31	New	-	E
			32	A	-	E
			33	New	-	E
			34	New	-	E
			35	A	A1	E
			36	A	-	E
			37	New	-	E
			38	New	-	E
			39	New	-	E
			40	New	-	E
			41	New	-	E
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No 737	
J. Dodd	Feb. 9, 2004	HEATHTECNA			Page 7.18 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H2632, cont.			42	A	-	E
			43	New	-1	E
			44	New	-	E
			45	New	-1	E
			46	New	-	E
H2727		Details – SpaceMaker	PL	New	-1	E
			1	New	-	E
			2	A	A1	E
			3	New	-1	E
			4	A	-	E
H3205	-1 [123]	Bin Extension Installation (ATIX 2) 737	PL	New	-1,-2	G
			1	New	-	D
			2	New	-	D
			3	New	-1,-2	G
			4	New	-	D
			5	New	-	D
			6	A	A1,A2	G
			7	New	-1,-2	G
			8	New	-1,-2	G
			9	New	-1,-2	G
			10	A	A1,A2	G
			11	New	-1,-2	G
</						


**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H3206		Bin Extension Installation - (ATIX 2) 737	PL	New	-1	H
			1	New	-	F
			2	New	-1	H
			3	New	-	F
			4	New	-	F
			5	New	-1	H
			6	New	-1	H
			7	New	-1	H
			8	New	-1	H
H3210	-1 [123]	Placard Installation - Emergency Equipment	PL	New	-1,-2	F
			1	A	-	F
			2	New	-	D
			3	A	-	F
			4	A	-	F

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H3211	-1 [123]	Placard Installation - Seat Row	PL 1 2	A New New	- - -	E D D
H3225		Metal Details – Bin Modification	PL 1 2 3	A New A C	A1 - - -	F E E H
H3227		Bin Modification - Forward, Right Hand (737)	PL 1 2	New New New	-1 - -	F F F
H3228		Panel Assembly - Bin Divider	PL 1 2	New New New	-1 -1 -1,-2	F F F
H3229		End Filler Assembly - ATIX 2 (Edge Guard) 18” Aisle	PL 1 2 3 4 5	New New New New New	- - - - -	F F F F F
H3230		End Cap Assembly - ATIX 2 (Edge Guard) 18” Aisle	PL 1 2 3 4	New New New New	- - - -	F F F F
H3265		Door Assembly - ATIX 2a	PL 1 2	C B B	C1,C2 B1 -	H E H
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	<div>HEATHTECNA</div> <div>Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226</div>			Model No	
J. Dodd	Feb. 9, 2004				737	
					Page 7.21 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H3269		Edge Guard – Lower	PL 1	New New	- -1	F F
H3272		Gap Cover - ATIX 2a	PL 1	New New	- -	C C
H3278		Placard, Seat Row	BK	F	F1	G
H3279		Detail – Edge Guard, Lower	PL 1 2	C B B	- - -	E E E
H3280		Panel Assembly – Filler ATIX 2 (Edge Guard)	PL 1 2 3 4 5 6 7 8	D New New A A New New New New	- -1,-2 -1,-2 A1 A1 -1 - - -	E C C C C C E E E
H3293		End Filler Assembly - ATIX 2 (Edge Guard)	PL 1 2 3 4 5 6 7 8 9 10 11	B A New New New A A New A New New	B1 - - - - - - - - - - -	F E C C C C E F E F E E
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date				Model No	
J. Dodd	Feb. 9, 2004	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			737 Page 7. 22 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H3294		Panel Assembly, End Cap – ATIX 2 (Edge Guard)	PL	B	-	F
			1	A	-	E
			2	New	-	C
			3	New	-	C
			4	New	-	E
			5	A	-	E
			6	New	-	E
			7	A	A1	F
			8	New	-	E
			9	New	-	F
			10	New	-	F
H3297		Bullnose Assembly - ATIX 2 (Edge Guard)	PL	C	-	E
			1	New	-	C
			2	A	-	E
			3	B	-	E
			4	New	-1	E
H3637		Switch Box Assembly	PL	B	-	E
			1	A	-	E
			2	B	B1	E
			3	A	A1	E
			4	A	-	E
			5	B	-	E
			6	A	-	E
			7	New	-	E
			8	New	-	E

Prepared by	Date	Title	Report No.
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit	HPD-DL-68
Checked by.	Date	<div>HEATHTECNA</div> <div>Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226</div>	Model No
J. Dodd	Feb. 9, 2004		737
			Page 7.23 REV H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H3665		Details – Closet	PL	C	C1	E
			1	B	-	E
			2	B	B1	E
			3	New	-	E
			4	A	-	E
			5	A	-	E
			6	A	A1	E
			7	A	-	E
			8	New	-	E
H3667		Details – Coat Rail	PL	A	-	H
			1	B	-	H
			2	B	-	E
H3668		Details – Tambour Door	PL	B	-	E
			1	A	-	E
			2	B	-	E
			3	B	-	E
			4	B	-	E
			5	B	-	E
			6	New	-	E
			7	New	-	E
			8	A	-	E
			9	New	-	E
H4417		Identification Placard	BK	C	-	H
H4841	[135,137]	Wiring Change Diagram - Qantas Airways 737-400 Systems Modification	BK	H	-	H
Prepared by C. Zilinek	Date Feb. 9, 2004	Title Drawing List- ATIX 2 Interior Retrofit Kit	Report No. HPD-DL-68			
Checked by J. Dodd	Date Feb. 9, 2004	HEATHTECNA Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226				Model No 737 Page 7.24 REV H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H4842	-1 [125,135,137,143]	Installation – Cabin Audio Seat Wiring	PL	New	-	E
			1	B	-	G
			2	B	-	F
H4843		Wire Kits – Shipside	BK	C	-	F
H4844	-1 [125,135,143] -3 [125,137,143] -5 [137]	Install – Ships Wiring	PL	E	-	H
			1	D	-	G
			2	D	-	G
			3	B	-	G
			4	B	-	G
			5	B	-	G
			6	B	-	G
			7	D	-	G
			8	E	-	H
			9	C	-	H
			10	D	-	H
			11	C	-	H
			12	B	-	H
			13	B	-	F
			14	New	-	E
			15	A	-	F
			16	B	-	G
			17	A	-	F
18	New	-	F			
H4845		Wire Kits – Furniture	BK	E	-	F

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H5420		Panel Assembly - Forward Left Hand Closet 737	PL	D	D1,D2	F
			1	F	-	E
			2	D	-	E
			3	A	-	E
			4	B	B1	E
			5	F	-	E
			6	C	-	E
			7	A	-	E
			8	A	-	E
			9	A	-	E
			10	New	-	E
			11	A	-	E
			12	B	-	E
			13	A	-	E
			14	B	-	E
			15	New	-	E
			16	A	-	E
			17	B	-	E
			18	F	-	E
			19	C	-	E
			20	A	-	E
			21	B	-	E
			22	B	B1	E
			23	New	-1	E
			24	A	-	E
			25	C	-	E
			26	New	-	E
			27	E	-	E
			28	D	-	F
			29	New	-	E
			30	A	-	E
			31	B	B1	E
			32	New	-	E
			33	B	B1	E
			34	A	A1	E
			35	A	-	E
			36	New	-	E
			37	A	-	E
			38	A	A1,A2	E
			39	New	-	E
			40	New	-1,-2	E
			41	New	-	E
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No	
J. Dodd	Feb. 9, 2004	HEATHTECNA			737	
					Page 7. 26 REV H	

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H5420, cont.			42	A	-	E
			43	A	-	E
			44	A	-	E
			45	A	-	E
			46	B	-	E
			47	New	-	E
			48	New	-	E
			49	New	-	E
			50	New	-	E
			51	New	-	E
			52	New	-	E
			53	New	-	E
			54	New	-	E
			55	New	-	E
			56	A	-	E
			57	A	-	E
			58	New	-	E
			59	New	-	E

Petitioner C&D Zodiac, Inc. – Exhibit 1019 - Page 75

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H5425		Machined Details - Forward Left Hand Closet, 737	PL	D	-	E
	1		A	-	E	
	2		A	-	E	
	3		A	-	E	
	4		New	-	E	
	5		A	-	E	
	6		New	-	E	
	7		A	-	E	
	8		New	-	E	
	9		New	-	E	
	10		New	-	E	
	11		New	-	E	
	12		New	-1	E	
	13		New	-	E	
	14		New	-	E	
	15		New	-	E	
	16		New	-	E	
	17		New	-1	E	
	18		New	-	E	
	19		New	-	E	
	20		A	-	E	
	21		New	-1	E	
	22		New	-	E	
	23		A	-	E	
	24		New	-	E	
	25		New	-	E	
	26		New	-	E	
	27		New	-	E	
	28		A	-	E	
	29		A	-	E	
	30		New	-	E	
	31		New	-	E	
	32		New	-	E	
	33		New	-	E	
	34		New	-	E	
	35		New	-	E	
	36		A	-	E	
	37		A	-	E	
	38		New	-	E	
	39		New	-	E	
	40		New	-	E	
	41		New	-	E	
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No	
J. Dodd	Feb. 9, 2004	HEATHTECNA			737	
					Page 7. 28 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H5425, cont.			42	New	-1	E
			43	New	-1	E
			44	New	-	E
			45	New	-	E
			46	New	-	E
			47	New	-	E
			48	New	-	E
			49	New	-	E
			50	New	-	E
			51	New	-1	E
H5427		Formed Details - Forward Left Hand Closet, 737	PL	C	-	E
			1	A	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
			5	New	-	E
			6	New	-	E
			7	New	-	E
			8	A	A1,A2,A3	E
			9	New	-	E
			10	A	-	E
			11	New	-	E
			12	A	-	E
			13	New	-1	E
			14	New	-1	E
			15	New	-1	E
			16	A	-	E
			17	New	-	E
			18	A	-	E
			19	New	-	E
			20	New	-	E
			21	A	-	E
			22	A	-	E
			23	New	-	E
			24	New	-	E
			25	A	A1	E
			26	New	-	E
			27	New	-	E
			28	New	-	E
			29	New	-	E
Prepared by	Date	Title				Report No.
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit				HPD-DL-68
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226				Model No 737
J. Dodd	Feb. 9, 2004	HEATHTECNA				Page 7. 29 REV H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H5427, cont.			30	New	-1	E
			31	New	-1	E
			32	New	-	E
			33	New	-	E
			34	New	-	E
			35	New	-	E
			36	New	-	E
			37	New	-	E
			38	New	-	E
			39	New	-	E
			40	New	-	E
			41	New	-	E
	H5930		Wiring Change Diagram – No Smoking Signs – Modification	BK	A	-
H5972	-1 [155]	737-400 IFE Power Cut-Off Switch Installation	PL	New	-1,-2	H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6014		Panel Assembly – Closet	PL	C	C1,C2	H
			1	B	-	H
			2	B	-	H
			3	D	-	H
			4	B	-	G
			5	A	-	F
			6	B	-	H
			7	A	-	F
			8	A	-	F
			9	B	-	H
			10	A	A1	H
			11	C	-	H
			12	B	-	H
			13	C	-	H
			14	A	-	F
			15	B	-	G
			16	A	-	F
			17	New	-	E
			18	A	A1	G
			19	A	-	F
			20	A	-	H
			21	A	-	H
			22	A	-	H
			23	New	-	F
			24	A	-	H
			25	New	-	F
			26	A	-	H
			27	New	-	F
			28	New	-	F
			29	New	-	F
			30	A	A1	H
			31	New	-	H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6015		Formed Details – Closet	PL	B	-	H
			1	A	-	E
			2	A	-	E
			3	A	-	E
			4	B	-	F
			5	A	-	E
			6	A	-	E
			7	B	-	F
			8	B	-	F
			9	A	-	E
			10	B	-	F
			11	A	-	E
			12	A	-	E
			13	A	-	E
			14	A	-	E
			15	B	-	H
			16	B	-	F
			17	New	-	E
			18	New	-	E
			19	A	A1	H
			20	A	-	E
			21	A	-	E
			22	A	-	E
			23	C	-	H
			24	B	B1	H
			25	A	A1	H
			26	A	-	E
			27	New	-	F
			28	New	-	F
			29	New	-1	G
			30	New	-	F
			31	New	-	F
			32	New	-	F
			33	New	-	F
			34	New	-1	G
			35	New	-	F
			36	New	-1,-2	H
			37	New	-	H
Prepared by	Date	Title				Report No.
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit				HPD-DL-68
Checked by.	Date	<div>Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226</div>				Model No
J. Dodd	Feb. 9, 2004	<div>HEATHTECNA</div>				737
						Page 7. 32 REV H


**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6016		Machined Details – Closet	PL	A	A1,A2,A3	H
			1	New	-	E
			2	New	-	E
			3	A	-	H
			4	A	-	H
			5	New	-	E
			6	A	-	H
			7	A	-	H
			8	A	-	H
			9	A	-	H
			10	A	-	H
			11	New	-	E
			12	New	-	E
			13	New	-	E
			14	New	-	E
			15	New	-	E
			16	New	-	E
			17	New	-	E
			18	New	-	E
			19	New	-	E
			20	New	-	E
			21	New	-	E
			22	New	-1	F
			23	New	-	E
			24	A	-	F
			25	A	-	F
			26	A	-	F
			27	New	-1	F
			28	New	-1	E
			29	B	-	F
			30	New	-	E
			31	New	-	F
			32	New	-1	F
			33	New	-	H
			34	New	-	H
			35	New	-	H
			36	New	-	H
			37	New	-	H
			38	New	-	H
			39	New	-	H
			40	New	-	H
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No 737	
J. Dodd	Feb. 9, 2004	HEATHTECNA			Page 7.33 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV														
H6051	-1 [129]	Installation – Forward Left Hand, 737-400	PL 1	New C	-1,-2,-3,-4 -	H H														
H6052		Closet Assembly - Forward Left Hand Closet	PL 1 2 3	A B A A	A1,A2,A3 - - -	H G F F														
H6053		Component Assembly - Forward Left Hand Closet	PL 1 2 3	New New A New	-1 - - -	F E F E														
H6054		Bonded Assembly - Forward Left Hand Closet	PL 1 2	New New New	- - -	E E E														
H6055		Panel Assembly - Forward Left Hand Closet	PL 1 2 3 4 5 6 7 8 9 10	New New B D B A New New A A New	-1,-2,-3,-4,-5 - - - - - - - - - -1	F E F H F F E E E F E														
H6056		Tambour Door Assembly - Forward Left Hand Closet	PL 1 2	New A New	-1,-2 - -	F F E														
<table border="1"> <tr> <td>Prepared by C. Zilinek</td><td>Date Feb. 9, 2004</td><td colspan="3">Title Drawing List- ATIX 2 Interior Retrofit Kit</td><td colspan="2">Report No. HPD-DL-68</td></tr> <tr> <td>Checked by. J. Dodd</td><td>Date Feb. 9, 2004</td><td colspan="3"> HEATHTECNA Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226 </td><td>Model No 737</td><td>Page 7. 34 REV H</td></tr> </table>							Prepared by C. Zilinek	Date Feb. 9, 2004	Title Drawing List- ATIX 2 Interior Retrofit Kit			Report No. HPD-DL-68		Checked by. J. Dodd	Date Feb. 9, 2004	HEATHTECNA Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No 737	Page 7. 34 REV H
Prepared by C. Zilinek	Date Feb. 9, 2004	Title Drawing List- ATIX 2 Interior Retrofit Kit			Report No. HPD-DL-68															
Checked by. J. Dodd	Date Feb. 9, 2004	HEATHTECNA Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No 737	Page 7. 34 REV H														


**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6057		Details – Sheet Metal, Forward Left Hand Closet	PL	New	-1,-2	G
			1	New	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
			5	New	-	E
			6	New	-	E
			7	A	-	F
			8	New	-	E
			9	New	-	G
H6058		Details – Machined, Forward Left Hand Closet	PL	New	-1,-2,-3,-4	H
			1	New	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
			5	New	-	E
			6	New	-	E
			7	A	-	E
			8	A	-	E
			9	New	-	E
			10	New	-	E
			11	A	-	F
			12	New	-	E
			13	New	-1	H
			14	New	-	F
H6061	-1 [129]	Installation – Forward Right Hand Closet	PL	New	-	E
			1	New	-	E
H6062		Closet Assembly - Forward Right Hand Closet	PL	B	B1,B2,B3,B4,B5, B6	H
			1	C	C1,C2,C3,C4	H
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date				Model No	
J. Dodd	Feb. 9, 2004	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			737 Page 7. 35 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6063		Compartment Assembly - Forward Right Hand Closet	PL	A	-	H
			1	B	-	F
			2	New	-1,-2	H
H6064		Bonded Assembly - Forward Right Hand Closet	PL	New	-1	F
			1	New	-	E
			2	A	-	F
H6065		Panel Assembly - Forward Right Hand Closet	PL	A	-	F
			1	A	-	F
			2	C	-	F
			3	A	A1	G
			4	A	-	F
			5	A	-	F
			6	New	-	E
			7	New	-1	F
			8	New	-1	F
			9	A	A1	F
			10	New	-	E
			11	New	-1	F
			12	New	-	E
			13	B	-	F
			14	B	-	F
			15	B	-	F
			16	New	-	F
H6066		Door Assembly - Forward Right Hand Closet	PL	New	-1,-2	F
			1	A	A1	F
			2	A	A1	F

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6067		Sheet Metal Details - Forward Right Hand Closet	PL	A	A1	G
			1	New	-	E
			2	A	-	E
			3	New	-	E
			4	New	-	E
			5	New	-	E
			6	New	-	E
			7	A	A1	G
			8	New	-	E
			9	New	-	E
H6068		Machined Details - Forward Right Hand Closet	PL	B	B1	F
			1	New	-	E
			2	C	-	F
			3	New	-	E
			4	New	-	F
H6069		Miscellaneous Details - Forward Right Hand Closet	PL	New	-1	E
			1	New	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
H6071	-1 [129]	Installation – Aft Left Hand Closet	PL 1	B B	- -	H H
H6072		Closet Assembly - Aft Left Hand Closet	PL 1	A A	A1,A2 A1	H H
H6073		Compartment Assembly - Aft Left Hand Closet	PL	A	-	F
			1	A	-	F
			2	A	-	F
Prepared by	Date	Title				Report No.
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit				HPD-DL-68
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226				Model No 737
J. Dodd	Feb. 9, 2004					Page 7. 37 REV H

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6074		Bonded Assembly - Aft Left Hand Closet	PL	A	-	F
			1	A	-	F
			2	New	-1	E
			3	New	-	E
H6075		Panel Assembly - Aft Left Hand Closet	PL	A	A1,A2,A3,A4	F
			1	A	-	F
			2	New	-1	E
			3	B	-	F
			4	A	-	F
			5	B	-	E
			6	New	-	E
			7	New	-	E
			8	B	-	F
			9	New	-	E
			10	New	-	E
			11	New	-	E
			12	A	-	E
			13	B	B1	H
			14	A	-	E
			15	A	-	E
			16	New	-	E
H6076		Door Assembly - Aft Left Hand Closet	PL	New	-1,-2,-3	H
			1	B	B1	H
			2	B	B1	H
			3	B	B1	H
			4	B	B1	H
Prepared by	Date	Title			Report No.	
C. Zilinek	Feb. 9, 2004	Drawing List- ATIX 2 Interior Retrofit Kit			HPD-DL-68	
Checked by.	Date	Heath Tecna Inc. 3225 Woburn Street Bellingham, Washington 98226			Model No	
J. Dodd	Feb. 9, 2004	HEATHTECNA			737	
					Page 7. 38 REV H	

**Drawing List NO. HPD-DL-68 for H1570 ATIX 2 Interior Retrofit Kit for
Model 737-400 Series Airplanes**

DWG NO.	Dash NO.	Title	SH NO.	REV	ADCN	DL REV
H6077		Sheet Metal Details - Aft Left Hand Closet	PL	New	-	E
			1	New	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
			5	New	-1	F
			6	New	-1	E
			7	New	-	E
			8	New	-1	F
			9	New	-1	F
H6078		Machined Details - Aft Left Hand Closet	PL	New	-1,-2,-3	F
			1	New	-	E
			2	New	-	E
			3	New	-	E
			4	New	-	E
			5	New	-	E
			6	New	-	E
			7	A	-	F
			8	New	-	E
			9	New	-	E
			10	New	-	E
			11	New	-	E
			12	A	-	F
			13	New	-	E
			14	New	-	F
H6080	-1 [129]	Equipment Installation	PL	A	-	F
			1	A	-	F
H6081	-1 [129]	Installation – Aft Right Hand Closet	PL	A	A1,A2	G
			1	A	A1,A2	G